

Parameter	Symbol	Unit	Min	Typ	Max	Note
	λ					
	λ					

Note 1: Sensitivity for 10G PRBS 2^{31}-1 and BER better than or equal to 10E-12

Note 2: The stressed sensitivity value in the table are for system level BER measurements which include the effects of CDR circuit.